

# Oil Field Environmental Incident Summary

**Incident:** 20141225103042      **Date/Time of Notice:** 12/25/2014 10:30

**Responsible Party:** Hess Corporation

**Well Operator:** HESS CORPORATION

**Well Name:** Hess Corporation 8-inch Gas Gathering Pipeline ROW

**Field Name:** KEENE

**Well File #:**

**Date Incident:** 12/24/2014      **Time Incident:** 09:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153

**Rng:** 95

**Sec:** 20

**Qtr:** SW

**Location Description:** Hess Corporation 8-inch Gas Gathering Pipeline ROW

**Submitted By:** Jason Henry

**Received By:**

**Contact Person:** Jason Henry  
3015 16th Street SW, Suite 20  
Minot, ND 58701

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.2 Mile

**Distance Nearest Water Well:** 0.2 Mile

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.5	Barrels	0.5	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

The release has been secured, and the pipeline is de-pressured awaiting repairs to be made.

**Areal Extent:**

**Potential Environmental Impacts:**

There were no potential receptors observed in the immediate vicinity of the release location. The pipeline will be repaired, and the impacted soil will be excavated, stockpiled, and transported off-site for disposal at a properly permitted facility.

**Action Taken or Planned:**

The pipeline will be repaired, and the impacted soil will be excavated, stockpiled, and transported off-site for disposal at a properly permitted facility.

**Wastes Disposal Location:** At a properly permitted disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 12/26/2014    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release from a pipeline leak was not contained according to the report. Followup is necessary.

---

**Date:** 4/8/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site at 14:15 p.m. The weather was clear, 46 °F, with the wind from the east at 5-10 mph. There are new pipelines being installed in this area by another company. I could not find the incident site; I will request more information on the site. More followup needed.

---

**Date:** 9/3/2015    **Status:** Inspection

**Author:** Washek, Sandi

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on-site at 2:45 pm Sunny 86 degrees with wind out of the SW at 15 miles/hr. The start of leveled soil GPS location is N 48.05609 W 103.92854 The leveled soil runs northwest through pastureland. The exact location of the spill could not be found since the area has been filled in and leveled. There was also no visible staining of soil on the site. No water ways were impacted.

---

**Date:** 8/22/2016    **Status:** Correspondence

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received an email with a Site Assessment Report (SAR) from the company contact. SAR added to the incident folder. More follow-up needed.